# RHIC MAINTENANCE SCHEDULE FOR SEPTEMBER 6, 2001

# **RESULTS**(1630hrs, Sept. 6, 2000)

R. Zaharatos - September 5, 2001

# SHUTDOWN PERIOD: 0800HRS TO 1600HRS (SEB SET-UP DURING THIS PERIOD)

#### **PRIMARY JOBS**

# **RHIC IR's**

# **BRAHMS**

C 1. Replace drift chamber

#### **PHOBOS**

C 1. Work on experimental equipment

#### **PHENIX**

**C** 1. Shielding work for muID

#### **STAR**

**C** 1. EMCal work

# RHIC TUNNEL

- C 1. Investigate excessive back-pressure on domestic water used for STAR Tower make-up(Water Sys. Grp.) Sect. 6. \*Problem now understood. Design change to be implemented at future date.
- C 2. Fire alarms system testing Sectors 1002, 1006, 1008(Fire Alarms Elect., 2hrs.ea.)
- C 3. Remove VME chassis from rack in 1003A Alcove(Controls Grp.)
- C 4. Air conditioning P.M.'s for 5A,B, and C. \* 5A and B found tripped, readjusted air flow.

# RHIC SUPPORT BLDGS.

- C 1. Investigate quench link erroneous P.S. interlocks(1002A, 1004B) \* Checked for loose AC connections on large QPA's tightened several
- C 2. Cryo Back-up compressors(1005H) maintenance
- C 3. Investigate tripping of substation breaker for 1000P(PK/Bruno) \* Repaired breaker fingers. Removed low voltage interlock circuit.
- C 4. Investigate 1004A intermittent gnd. fault. \* All rotating equip. checked OK. Other checks=no cause found.

# Other Systems

**C** 1. Clean strainers on Tower 3

# TESTING/CONDITIONING

- **RS** 1. RF System conditioning.
- C 2. Testing of Snake P.S. at 9C into dummy load(Bruno)